

Practical Air Comfort Indicator



Dry



Humidity < 30%

Comfort



30% < Humidity < 60%

20°C < Temperature < 26°C

Wet



Humidity > 60%

Why Choose Us

	ThermPro	OTHERS
Temperature Range	-50°C - 70°C	0°C - 50°C
Temperature Accuracy	± 1° C	± 2° - 3°C
Humidity Accuracy	± 2-3%	± 5%
Max/Min Records	Yes	No





Humidity
Display

Temperature
Display



Large LCD Display



Stands Upright for
Tabletop Use



Battery Included



Magnetic Backing

ThermPro Life Like A Pro!



Indoor Temperature & Humidity Monitor



Thermometer



Hygrometer



Comfort Indicator



10S refresh



Max/Min
Records



°C/°F Switcher



Strong Magnet



Foldable Stand

ThermPro

Current humidity

62%



DRY



COMFORT



WET

Comfort level

Current Temperature

76.1°F

Max/Min humidity

low 52% 69% high

Max/Min Temperature

low 69.5°F 78.5°F high



Compact & Portable

Pocket-Sized for Portability

